preferable.

# DeSoto, Inc. MATERIAL SAFETY DATA SHEET

MMS 405

Rev. B Enamel Epoxy Comonflage

FOR COATINGS, RESINS AND RELATED MATERIALS

		and the second second second			
S OF BRED	7	(Approved by U.S	3. Department of	f Labor	"Essentially Similar" to
*** 12-18-72					
		A CONTRACTOR OF THE CONTRACTOR	•		

Form OSHA-20)

12-10-72				- CAPAL	ronflagu
	Section I			:	<del></del>
MANUFACTURER'S NAME DeSoto, Inc.					
STREET ADDRESS 1700 S. Mt. Prospect Rd. CIT	Y, STATE, AND ZIP	code Des	Plaines,	Illino	is 60018
EMERGENCYTELEPHONE NO. (312) 296-6611					
PRODUCT CLASS Epoxy	MANU	FACTURERS COD	E IDENTIFICATIO	N	
TRADE NAME	522-	-723 Base			
Section II — HAZ	ARDOUS	INGREDIE	NTS		
INGREDIENT	PERCENT	TI PPM	LV mg/m³	LEL	VAPOR PRESSURE
					@ 20°C.
Butyl Acetate n-Butanol Methyl Ethyl Ketone	22.8 1.9 17.8	150 100 200	710 300 590	1.7 1.4 1.8	8 mm 4.3 70
Section III -	- PHYSIC	AL DATA			
BOILING RANGE	VAPOR DE	NSITY	HEAVIER,	LIGHTER	THAN AIR
EVAPORATION RATE FASTER X SLOWER, THAN ETHER	PERCENT VOLATI BY VOLUME	62.5	WEIGHT PER GALLON	10.3	
Section IV — FIRE AN	D EXPLOS	ION HAZA	ARD DATA		
Red label, flammable, less than 80°F.	FLASH POI	22 <sup>O</sup> F	(TOC)		LEL See II
EXTINGUISHING MEDIA Use National Fire Protec (Carbon dioxide, dry chem	tion Asso	ciation ( foam)	Class B e	xtingui	lshers
unusual fire and explosion Hazards Keep containers electrical equipment, sparks and open ten exposed to extreme heat. Do not	flame. apply to	Closed co	ontainers faces.	may ex	xplode
closed containers to prevent pressure	ineffec	tive. Wa	ater may	be used	to cool

closed containers to prevent pressure build-up and possible auto ignition or explosion when exposed to extreme heat. If water is used, fog nozzles are

## Section V — HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE Inhalation: Anesthetic. Irritation of the respiratory tract or acute nervous system depression characterized by headache, dizziness, staggering gait, confusion, unconsciousness or coma.

Skin or Eye Contact: Primary Irritation

Keep warm and quiet. Notify a physician. Skin Contact: Wash affected areas with water. Remove contaminated clothing. Consult a physician. Eye Contact: Flush with water for 15 minutes. Consult a physician.

Section VI	_	<b>REACT</b>	<b>IVIT</b>	Y DATA
------------	---	--------------	-------------	--------

STABILITY UNSTABLE X STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid)

HAZARDOUS DECOMPOSITION PRODUCTS

CO and CO<sub>2</sub> on combustion

HAZARDOUS POLYMERIZATION MAY OCCUR X WILL NOT OCCUR

CONDITIONS TO AVOID

### Section VII — SPILL OR LEAK PROCEDURES

breathing vapors. Ventilate area. Remove with inert absorbent and non-sparking tools. Dispose in accordance with local, state and federal regulati Incinerate in approved facility. Do not incinerate closed containers.

#### Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION In outdoor or open areas use Bureau of Mines approved mechanical filter respirator.

In restricted ventilation areas use Bureau of Mines approved chemical-mechanical filters.

In confined areas use Bureau of Mines approved air line type respirators or hoods.

VENTILATION Provide general dilution or local exhaust ventilation in volume pattern to keep TLV of most hazardous ingredient in Section II below acceptable limit, LEL in Section IV below stated limit.

PROTECTIVE GLOVES Required for prolonged or repeated contact.

EYE PROTECTION Use safety eyeware designed to protect against splash of liquids.

OTHER PROTECTIVE EQUIPMENT Prevent prolonged skin contact with contaminated clothing.

#### Section IX — SPECIAL PRECAUTIONS

precautions to be taken in handling and storing. Do not store above  $120^{\rm o}$ F. Store large quantities in buildings designed and protected for storage of flammable liquids.

OTHER PRECAUTIONS Do not take internally. Containers should be grounded when pouring. Avoid free fall of liquid in excess of a few inches. Do not flame cut, braze or weld without Bureau of Mines approved respirator or appropriate ventilation. Observe warnings.